



Office of Transport Safety Investigations

RAIL SAFETY INVESTIGATION REPORT

TRACK WORKER FATALITY

BAAN BAA

22 MAY 2006



RAIL SAFETY INVESTIGATION REPORT

TRACK WORKER FATALITY

BAAN BAA

22 MAY 2006

*Released under the provisions of
Section 45C(2) of the Transport Administration Act 1988 and
Section 67(2) of the Rail Safety Act 2002*

Investigation Reference 04272

Published by: The Office of Transport Safety Investigations
Postal address: PO Box A2616, Sydney South, NSW 1235
Office location: Level 17, 201 Elizabeth Street, Sydney NSW 2000
Telephone: 02 9322 9200
Accident and incident notification: 1800 677 766
Facsimile: 02 9322 9299
E-mail: info@otsi.nsw.gov.au
Internet: www.otsi.nsw.gov.au

This Report is Copyright. In the interests of enhancing the value of the information contained in this Report, its contents may be copied, downloaded, displayed, printed, reproduced and distributed, but only in unaltered form (and retaining this notice). However, copyright in material contained in this Report which has been obtained by the Office of Transport Safety Investigations from other agencies, private individuals or organisations, belongs to those agencies, individuals or organisations. Where use of their material is sought, a direct approach will need to be made to the owning agencies, individuals or organisations.

Subject to the provisions of the *Copyright Act 1968*, no other use may be made of the material in this Report unless permission of the Office of Transport Safety Investigations has been obtained.

THE OFFICE OF TRANSPORT SAFETY INVESTIGATIONS

The Office of Transport Safety Investigations (OTSI) is an independent NSW agency whose purpose is to improve transport safety through the investigation of accidents and incidents in the rail, bus and ferry industries. OTSI investigations are independent of regulatory, operator or other external entities.

Established on 1 January 2004 by the Transport Administration Act 1988, and confirmed by amending legislation as an independent statutory office on 1 July 2005, OTSI is responsible for determining the causes and contributing factors of accidents and to make recommendations for the implementation of remedial safety action to prevent recurrence. Importantly, however, OTSI does not confine itself to the consideration of just those matters that caused or contributed to a particular accident; it also seeks to identify any transport safety matters which, if left unaddressed, might contribute to other accidents.

OTSI's investigations are conducted under powers conferred by the Rail Safety Act 2002 and the Passenger Transport Act 1990. OTSI investigators normally seek to obtain information cooperatively when conducting an accident investigation. However, where it is necessary to do so, OTSI investigators may exercise statutory powers to interview persons, enter premises and examine and retain physical and documentary evidence.

It is not within OTSI's jurisdiction, nor an object of its investigations, to apportion blame or determine liability. At all times, OTSI's investigation reports strive to reflect a "Just Culture" approach to the investigative process by balancing the presentation of potentially judgemental material in a manner that properly explains what happened, and why, in a fair and unbiased manner.

Once OTSI has completed an investigation, its report is provided to the NSW Minister for Transport for tabling in Parliament. The Minister is required to table the report in both Houses of the NSW Parliament within seven days of receiving it. Following tabling, the report is published on OTSI's website at www.otsi.nsw.gov.au.

OTSI cannot compel any party to implement its recommendations and its investigative responsibilities do not extend to overseeing the implementation of recommendations it makes in its investigation reports. However, OTSI takes a close interest in the extent to which its recommendations have been accepted and acted upon. In addition, a mechanism exists through which OTSI is provided with formal advice by the Independent Transport Safety and Reliability Regulator (ITSRR) in relation to the status of actions taken by those parties to whom its recommendations are directed.

TABLE OF CONTENTS

| | |
|--|---------------|
| TABLE OF FIGURES | ii |
| TABLE OF PHOTOS | ii |
| TERMS OF REFERENCE | iii |
| EXECUTIVE SUMMARY | iv |
| PART 1 FACTUAL INFORMATION | 1 |
| Incident Synopsis | 1 |
| Incident Narrative | 1 |
| Location of the Accident | 5 |
| Train Information | 6 |
| Communication Equipment | 10 |
| Employee Information | 11 |
| Injuries | 11 |
| Medical and Toxicological Information | 11 |
| Meteorological Information | 13 |
| PART 2 ANALYSIS | 14 |
| Causation | 14 |
| Contributory Factors | 17 |
| Anticipation and Management of Risk | 24 |
| Adequacy of the Emergency Response | 26 |
| Other Safety Matters | 27 |
| Remedial Actions | 28 |
| Summary | 29 |
| PART 3 FINDINGS | 31 |
| Causation | 31 |
| Contributory Factors | 31 |
| Anticipation and Management of Risk | 32 |
| Effectiveness of the Emergency Response | 32 |
| Other Matters that would Enhance the Safety of Rail Operations | 32 |
| PART 4 RECOMMENDATIONS | 34 |
| Australian Rail Track Corporation Ltd | 34 |
| RailCorp | 35 |
| Southern & Silverton Railway Pty Ltd | 35 |
| The Independent Transport Safety and Reliability Regulator | 35 |
| Appendix 1: Sources and Submissions | 37 |

TABLE OF FIGURES

| | | |
|-----------|--|----|
| Figure 1: | Ballast wagon configuration and worker locations | 3 |
| Figure 2: | Incident location | 6 |
| Figure 3: | Hasler tape from locomotive KL81 | 19 |
| Figure 4: | Close-up of Hasler tape from locomotive KL81 | 19 |
| Figure 5: | Hasler tape from locomotive 602 | 20 |
| Figure 6: | Close-up of Hasler tape from 602 | 20 |
| Figure 7: | Comparison of speed traces for KL81 and 602 | 21 |
| Figure 8: | Planned ballast drops | 22 |

TABLE OF PHOTOS

| | | |
|-----------|--|----|
| Photo 1: | Ballast train 5M23 near Baan Baa | iv |
| Photo 2: | Ballast wagon | v |
| Photo 3: | Railway track and surrounding terrain at incident location | 6 |
| Photo 4: | Internal bracing of ballast wagon | 7 |
| Photo 5: | Ballast hopper side doors | 8 |
| Photo 6: | Ballast hopper door controls | 8 |
| Photo 7: | Ballast wagon walkways and steps | 9 |
| Photo 8: | Plough van at rear of 5M23 | 9 |
| Photo 9: | Plough blade and controls | 10 |
| Photo 10: | Location of strike point on hopper door | 14 |

